



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

GK20DKJ

DAF XF 530

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details

Reg. date	13/03/2020	VIN	XLRTGH4300G297417	Cab Type	SLEEPER CAB
Year	2020	Body Style	Tractor Unit	Gearbox	AUTOMATIC
Mileage	551,043 Km Not Warranted	CAP Clean	£14,050.00	Axle Combi	6x2
Fuel Type	Diesel	CAP Average	£13,200.00	Steering Combi	Mid-Lift
Colour	WHITE	CAP Below	£11,900.00	Rear Suspension	Air

WARNING LIGHTS ON DASH SLIDING 5TH WHEEL

Tyres





NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Front electric windows
- Cruise control
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning


Photos







Condition Check



Damage Photos



1: Dash Warning Lights
Displayed
No Action

2: Switches And Controls
Broken
Replace




3: Bonnet
Chipped
Multiple Chips

4: Bumper Front
Chipped
Multiple Chips



5: Panel Front
Cracked
Replace

6: Door Mirror Assy nsf
Missing
Replace



7: Wing nsf
Scratched
Over 25mm Not Thru Paint

8: Wing nsf
Scratched
Over 25mm Thru Paint



9: Wing Front Arch Extension ns
 Scratched (Painted)
 UpTo 25mm Thru Paint

10: Qtr Panel osr
 Cracked
 Replace



11: Panel Rear
 Scratched
 Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	Fault	DPF light illuminated	OK
		Service indicator light illuminated	OK
		Radio	OK
		Steering	OK