



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BV16ZLU

VOLVO FM 460

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Present

Details

Reg. date	01/04/2016	Colour	BLUE	Cab Type	GLOBETROTTER CAB
Year	2016	VIN	YV2XTY0GXGB759373	Gearbox	AUTOMATIC
Mileage	323,340 Km Not Warranted	Body Style	Cement Mixer	Axle Combi	8x2
Fuel Type	Diesel	MOT Due	31/05/2026	Rear Suspension	Steel

WARNING LIGHTS ON DASH SHEETING SYSTEM

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4



Features

- Manual sunroof
- Air conditioning
- Front electric windows
- Partial leather seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Screen Front
Cracked
Replace



3: Door Mirror Assy nsf
Broken
Replace

4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint

6: Door osf
Scratched
Over 25mm Thru Paint



7: Seat Base Cover osf
Holed
Over 3mm

8: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		