



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

WX19HLE

FUSO CANTER 9C18

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details					
Reg. date	03/05/2019	Colour	WHITE	Gearbox	AUTOMATIC
Year	2019	VIN	TYAFECX1GRDZ13394	Axle Combi	4x2
Mileage	97,374 Km Not Warranted	Body Style	Dropside	Rear Suspension	Steel
Fuel Type	Diesel	Cab Type	DAY CAB		

WARNING LIGHT ON DASH CIFA PC 506 / 309 D3B CONCRETE PUMP (YEAR 2018) C/W REMOTE


Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Cruise control
- Front electric windows
- Drivers airbag
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Rusted
Over 5mm



3: Door nsf
Chipped
Multiple Chips

4: Panel Rear
Rusted
Over 5mm



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint

6: Door osf
Scratched
Over 25mm Thru Paint



7: Seat Base Cover osf
Holed
Over 3mm

8: Door Pad osf
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	Fault
ABS light illuminated	OK	DPF light illuminated	OK