



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PK68BUW

Daf LF 180

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details

Reg. date	21/09/2018	VIN	XLRAEL1500L475324	Axle Combi	4x2
Year	2018	Body Style	Box Van	Rear Suspension	Steel
Mileage	28,644 Km Warranted	MOT Due	31/07/2026	Rear Doors	Barn
Fuel Type	Diesel	Cab Type	DAY CAB		
Colour	WHITE	Gearbox	MANUAL		

WARNING LIGHT ON DASH SIDE LOADING BARN DOOR, SOCKETS, SEATING AREA, SURROUND CAMERA SYSTEM

Tyres






NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4




Features

- Park assist camera


Photos







Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm

2: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



3: Door Mirror Assy osf
 Scuffed (Unpainted)
 Over 100mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK