



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**DK66JJV**

## Man TGL 12.220

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Buyer To Apply

### Details

Reg. date 15/12/2016

Year 2016

Mileage 766,137 Km Not Warranted

Fuel Type Diesel

Colour ORANGE

VIN WMAN15ZZ0HY351931

Body Style Tilt & Slide

MOT Due 31/10/2026

Cab Type CREW CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Air

ROGER DYSON 3500 KG BODY, WINCH, SURROUND CAMERA SYSTEM

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Air conditioning


## Photos







## Condition Check



## Damage Photos



1: Screen Front  
Chipped  
Over 10mm




2: Front TowEye Cvr  
Missing  
Replace



3: Bonnet  
Missing  
Replace

4: Bumper Front Moulding  
Broken  
Replace




5: Other  
N/A  
N/A

6: Door Mirror Assy nsf  
Scuffed (Unpainted)  
Over 100mm



7: Wing Front Arch Extension ns  
Scratched (Painted)  
Over 25mm Thru Paint

8: Bumper Rear  
Rusted  
Over 5mm



9: C Post os  
Scratched  
UpTo 25mm Thru Paint

10: Door osr  
Chipped  
Multiple Chips



11: Door osf  
Chipped  
Edge Chip

12: Wing Front Arch Extension os  
Scratched (Painted)  
Over 25mm Thru Paint



13: Door Mirror Assy osf  
Scuffed (Unpainted)  
Over 100mm

14: Seat Base Cover osf  
Holed  
Over 3mm



15: Handle Inner osf  
 Damaged  
 Replace

**Interior**

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK