



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PA19DNN

Mercedes-Benz Sprinter 316 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details		VIN		CAP Below	
Reg. date	27/08/2019	VIN	WDB9076332P099073	CAP Below	£6,900.00
Year	2019	Body Style	Panel Van L2	Gearbox	MANUAL
Mileage	97,739 Miles Warranted	MOT Due	29/11/2026	Gears	4
Fuel Type	Diesel	CAP Clean	£10,250.00		
Colour	WHITE	CAP Average	£8,875.00		

WARNING LIGHT ON DASH *EML & INJECTORS REQUIRE ATTN, STIFF CLUTCH* *BACK DOORS DO NOT OPEN* AIR COMPRESSOR EQUIPMENT, AD-BLUE, SIDE LOADING DOOR




Tyres
NSF
NSR
OSF
OSR
Spare

Features


- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Door nsf
Dented
Over 30mm

2: Sill Panel Trim ns
Missing
Replace



3: Bumper Front
Insecure
Action Required

4: Sill ns
Dented
Over 30mm



5: Door nsr
Dented
Over 30mm

6: Door nsr
Dented
Over 30mm



7: Sill ns
Dented
Over 30mm

8: Qtr Panel nsr
Dented
Over 30mm



9: Panel Rear
Chipped
1 To 5

10: Sill os
Dented
Over 30mm



11: Wing osf
Dented
Over 30mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK