



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

RV75NWZ

Volkswagen Crafter CR35 2.0 TDI 140PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details					
Reg. date	19/09/2025	VIN	WV1ZZZSY0S9067920	CAP Below	£25,250.00
Year	2025	Body Style	Panel Van LWB	Gearbox	MANUAL
Mileage	6,857 Miles Not Warranted	MOT Due	18/09/2028	Gears	6
Fuel Type	Diesel	CAP Clean	£29,200.00		
Colour	WHITE	CAP Average	£28,100.00		

WARNING LIGHT ON DASH AD-BLUE, SIDE LOADING DOOR, E/MIRRORS


Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Front parking sensor
- Front electric windows
- Park assist camera
- Rear parking sensor
- Air conditioning

Photos





Condition Check



Damage Photos



1: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK