

# VEHICLE INSPECTION REPORT

**LN14NLC**

## MERCEDES ATEGO 1824

### Inspection

### Vehicle

|     |          |
|-----|----------|
| VAT | Plus VAT |
| V5  | Present  |

### Details

|           |                          |                 |                   |            |          |
|-----------|--------------------------|-----------------|-------------------|------------|----------|
| Reg. date | 31/03/2014               | VIN             | WDB9505092L789349 | Gearbox    | MANUAL   |
| Year      | 2014                     | Body Style      | Curtainside       | Axle Combi | 4x2      |
| Mileage   | 500,153 Km Not Warranted | Service history | Yes               | Tail Lift  | Tuckaway |
| Fuel Type | Diesel                   | MOT Due         | 30/09/2025        |            |          |
| Colour    | WHITE                    | Cab Type        | SLEEPER CAB       |            |          |

SLEEPER CAB, TUCKAWAY TAIL LIFT, BARN DOOR  
\*WARNING LIGHT ON DASH\*

### Tyres

NSF

NSR

OSF

OSR

Spare

### Photos



