



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SP63JDZ

Ford Transit T300 2.2 TDCi 100PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details

Reg. date	30/09/2013	Body Style	Panel Van MWB	Gearbox	MANUAL
Year	2013	Service documents	Printout	Gears	6
Mileage	135,318 Miles Warranted	MOT Due	05/10/2026	Axle Combi	4x2
Fuel Type	Diesel	CAP Clean	£1,175.00	Rear Doors	Barn
Colour	WHITE	CAP Average	£920.00		
VIN	WF0XXTTFXDP43415	CAP Below	£625.00		

SINGLE SIDE LOAD DOOR


Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Front electric windows
- Central locking
- Cloth seat trim

Photos






DRFB		FORD	
0.53		e1x2007/46x0244	
4CP B		xWFOXXXTTFXDP43415x	
3G R		3025	kg
AA F		5225	kg
V6		1600	kg
		1760	kg
W(mm)		L(mm)	a(mm)
N 3300		FAF6	



Condition Check



Damage Photos



1: Carpets Front
Torn
Over 10mm



2: Sill os
Rusted
Over 5mm



3: Roof
Rusted
Over 5mm

4: Bonnet
Dented
With Paint Damage



5: Wing osf
Dented
With Paint Damage

6: Door osf
Rusted
Over 5mm



7: B Post os
Rusted
Over 5mm

8: Qtr Panel osr
Dented
With Paint Damage



9: Tailgate
Dented
With Paint Damage

10: Qtr Panel nsr
Rusted
Over 5mm



11: Door nsr
Dented
Over 30mm

12: B Post ns
Rusted
Over 5mm



13: Door nsf
Dented
With Paint Damage

Interior

Carpet Condition	Poor	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK