



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

ST62MFX

Ford Transit Connect T230 1.8 TDCi 90ps

| Inspection | | Vehicle | |
|-----------------|----|---------|-----------|
| Serious Damage? | No | VAT | Plus VAT |
| | | V5 | To Follow |

| Details | | | |
|-----------|----------------------------|-------------------|---------------|
| Reg. date | 31/01/2013 | Body Style | Panel Van LWB |
| Year | 2013 | Service documents | Printout |
| Mileage | 103,709 Miles Warranted | MOT Due | 04/02/2027 |
| Fuel Type | Diesel | CAP Clean | £830.00 |
| Colour | WHITE | CAP Average | £650.00 |
| VIN | WF0UXXTPUCS82736 | CAP Below | £425.00 |
| | | Gearbox | MANUAL |
| | | Gears | 5 |
| | | Axle Combi | 4x2 |
| | | Rear Doors | Barn |

SINGLE SIDE LOAD DOOR

| Tyres |
|-------|
| NSF |
| NSR |
| OSF |
| OSR |
| Spare |

Features


- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm



2: Sill os
Rusted
Over 5mm



3: Bonnet
Rusted
Over 5mm

4: Wing osf
Chipped
Multiple Chips



5: Flasher Side Repeater os
Broken
Replace

6: Door osf
Dented
With Paint Damage



7: Tailgate
Dented
With Paint Damage

8: Door nsr
Rusted
Over 5mm



9: Door nsf
Dented
With Paint Damage

Interior

| Carpet Condition | Average | Upholstery Condition | Average |
|--------------------------|---------|--|---------|
| Seat Condition | Average | Odour | No |
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |
| Windows | OK | Radio | OK |
| | | Steering | OK |