



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

YS73USW

Citroen Relay 35 2.2 BLUE HDI 140PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details					
Reg. date	31/10/2023	VIN	VF7YDBPFPCPG017131	CAP Below	£11,000.00
Year	2023	Body Style	Minibus	Gearbox	MANUAL
Mileage	15,397 Miles Not Warranted	MOT Due	30/10/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£13,800.00		
Colour	WHITE	CAP Average	£12,800.00		


WARNING LIGHT ON DASH AD-BLUE, SIDE LOADING DOOR, E/MIRRORS, WHEELCHAIR LIFT




Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Navigation system
- Front electric windows
- Park assist camera
- Rear parking sensor
- Air conditioning

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Wing nsf
Scratched
Over 25mm Not Thru Paint



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

4: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



5: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

6: Qtr Panel osr
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

OK
OK

Upholstery Condition
Odour

OK
No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK