



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**DP69VWE**

## Vauxhall Vivaro 2900 1.5d 100PS Dynamic

**Non Runner**

### Inspection

**Serious Damage?** No

### Vehicle

**VAT** Plus VAT

**V5** Present

### Details

**Reg. date** 30/11/2019

**VIN** VXEVBYHRKL7004319

**CAP Below** £3,400.00

**Year** 2019

**Body Style** Panel Van LWB

**Gearbox** MANUAL

**Mileage** 123,511 Miles Not Warranted

**MOT Due** Expired

**Gears** 6

**Fuel Type** Diesel

**CAP Clean** £5,050.00

**CAP Average** £4,375.00

**Colour** BLACK

\*NON-RUNNER, POWERS UP DOES NOT START\* TWIN SIDE LOAD DOOR, E/MIRRORS, AD-BLUE

### Tyres

NSF

NSR

OSF

OSR


Spare

## Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



3: Wing nsf  
Chipped  
Multiple Chips



4: Qtr Panel nsr  
Chipped  
Multiple Chips



5: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint

6: Door nsr  
Dented  
With Paint Damage



7: Door nsr  
Scratched  
Over 25mm Thru Paint

8: Door osr  
Chipped  
Multiple Chips

