



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**DU20TTK**

## Vauxhall Vivaro 2700 1.5d 120PS Sportive

**Non Runner**

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	30/06/2020	VIN	VXEVBYHVKL7020737	CAP Below	£4,025.00
Year	2020	Body Style	Panel Van LWB	Gearbox	MANUAL
Mileage	117,163 Miles Not Warranted	MOT Due	13/10/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£5,725.00		
Colour	BLACK	CAP Average	£5,025.00		

\*NON-RUNNER, POWERS UP DOES NOT START\* TWIN SIDE LOAD DOOR, E/MIRRORS, AD-BLUE

Tyres
NSF
NSR
OSF
OSR
Spare

## Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Panel Front  
Scratched  
Over 25mm Thru Paint



3: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint

4: Door nsf  
Scratched  
Over 25mm Thru Paint



5: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint

6: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



7: Door nsr  
Scratched  
Over 25mm Thru Paint

8: Bumper Rear  
Cracked  
Over 25mm



9: Door osr  
Scratched  
Over 25mm Thru Paint

10: Qtr Panel osr  
Dented  
Over 30mm



11: Door osf  
Scratched  
Over 25mm Thru Paint

12: Screen Front  
Chipped  
Over 10mm



13: Fascia Panel  
Missing  
Replace

14: Seat Base Cover nsf  
Soiled  
Heavy

## Interior

**Carpet Condition**  
**Seat Condition**

OK  
Poor

**Upholstery Condition**  
**Odour**

Poor  
No

Engine Runs

Fault