



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HX23YMF

Mercedes-Benz Atego 1223

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details

Reg. date	30/03/2023	Colour	WHITE	Cab Type	DAY CAB
Year	2023	VIN	W1T96700520629667	Gearbox	AUTOMATIC
Mileage	64,857 Km Warranted	Body Style	Pole Erection Unit	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	28/02/2027	Rear Suspension	Steel

PALFINGER PK 9.501 REMOTE CRANE (YEAR 2022), SURROUND CAMERA SYSTEM, AUTOGUIDE 40PXV AUGER

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Door nsf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

OK
OK

Upholstery Condition
Odour

OK
-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK