



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DA62PLN

Mercedes-Benz Actros 1842

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	01/02/2013	Colour	WHITE	Cab Type	STREAMSPACE CAB (2.3M, 170MM)
Year	2013	VIN	WDB9634032L725088	Gearbox	AUTOMATIC
Mileage	1,782,010 Km Warranted	Body Style	Tractor Unit	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	30/11/2026	Rear Suspension	Air

Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Air conditioning
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Bonnet
Rusted
Over 5mm

4: Door nsf
Chipped
Over 5mm



5: Wing Front Arch Extension ns
Broken
Replace

6: C Post ns
Poor Previous Repair
Poor Paint



7: Sill ns
Poor Previous Repair
Paint Flake

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK