



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PJ20ZFM

Mercedes-Benz Sprinter 314 Cdi

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details		Colour	WHITE	Gearbox	AUTOMATIC
Reg. date	18/08/2020	VIN	W1V9076352P255580	Gears	6
Year	2020	Body Style	Panel Van LWB	Rear Suspension	Steel
Mileage	350,398 Miles Warranted	MOT Due	19/08/2026	Rear Doors	Barn
Fuel Type	Diesel				



SINGLE SIDE LOAD DOOR


Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Bluetooth connection
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Sill os
Rusted
Over 5mm

2: Bonnet
Dented
Over 30mm



3: Roof
Rusted
Over 5mm

4: Door osf
Dented
With Paint Damage



5: Qtr Panel osr
Dented
With Paint Damage

6: Tailgate
Dented
Over 30mm



7: Badgedecal Rear
Broken
Replace

8: Qtr Panel nsr
Dented
Over 30mm



9: Sill ns
Dented
With Paint Damage

10: Door nsr
Rusted
Over 5mm

Interior

Carpet Condition -
Seat Condition -

Upholstery Condition -
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK