



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SP13WHD

Ford Transit T350 2.2 TDCI 100PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details

Reg. date	26/04/2013	Body Style	Tipper Double Cab	Gearbox	MANUAL
Year	2013	Service documents	Printout	Gears	6
Mileage	122,575 Miles Warranted	MOT Due	01/05/2026	Axle Combi	4x2
Fuel Type	Diesel	CAP Clean	£2,675.00	Rear Suspension	Steel
Colour	WHITE	CAP Average	£2,075.00		
VIN	WF0NXXTTFNCS05664	CAP Below	£1,375.00		

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Carpets Front
Torn
Over 10mm



2: Sill os
Rusted
Over 5mm



3: Bonnet
Dented
With Paint Damage

4: Wing of
Rusted
Over 5mm



5: Door of
Rusted
Over 5mm

6: B Post of
Rusted
Over 5mm



7: D Post of
Rusted
Over 5mm

8: Qtr Panel of
Dented
Over 30mm





9: Tailgate
Dented
With Paint Damage

10: Qtr Panel nsr
Dented
With Paint Damage



11: D Post ns
Rusted
Over 5mm

12: Sill ns
Rusted
Over 5mm



13: B Post ns
Rusted
Over 5mm

14: Door nsf
Rusted
Over 5mm



15: Wing nsf
Dented
With Paint Damage

16: Roof
Rusted
Over 5mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK