



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**DE19WUO**

## Isuzu N75 190

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

### Details

Reg. date	25/03/2019	VIN	JAANPR75MJ7100447	Axle Combi	4x2
Year	2019	Body Style	Dropside	Rear Suspension	Steel
Mileage	157,733 Km Warranted	MOT Due	31/03/2027	Tail Lift	Cantilever
Fuel Type	Diesel	Cab Type	DAY CAB		
Colour	BLUE/YELLOW	Gearbox	AUTOMATIC		

SERVICE SCHEDULE LIST AVAILABLE, SURROUND CAMERA SYSTEM

### Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features


- Park assist camera

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Up To 25mm Thru Paint



2: Door nsf  
Dented  
With Paint Damage



3: Door osf  
 Chipped  
 Multiple Chips

**Interior**

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK