



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PF20ABO

Mercedes-Benz Sprinter 314 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	31/07/2020	VIN	W1V9076352P255546	CAP Below	£4,550.00
Year	2020	Body Style	Panel Van L3	Gearbox	AUTOMATIC
Mileage	224,232 Miles Warranted	MOT Due	30/07/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£6,475.00		
Colour	WHITE	CAP Average	£5,650.00		

AD-BLUE, SIDE LOADING DOOR



Tyres
NSF
NSR
OSF
OSR
Spare

Features


- Rear parking sensor
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm

2: Sill ns
Dented
Over 30mm



3: Door nsr
Dented
Over 30mm

4: Qtr Panel nsr
Dented
Over 30mm



5: Sill ns
Dented
Over 30mm

6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Panel Rear
Chipped
Multiple Chips

8: Sill os
Dented
Over 30mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK