



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PF20JYK

Mercedes-Benz Sprinter 314 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details

Reg. date	24/08/2020	VIN	W1V9076352P256146	CAP Below	£5,025.00
Year	2020	Body Style	Panel Van L3	Gearbox	AUTOMATIC
Mileage	199,062 Miles Warranted	MOT Due	14/07/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£7,150.00		
Colour	WHITE	CAP Average	£6,250.00		

AD-BLUE, SIDE LOADING DOOR

Tyres

NSF
NSR
OSF
OSR
Spare

Features


- Rear parking sensor
- Front electric windows

Photos





Condition Check



Damage Photos



1: Qtr Panel nsr
Dented
Over 30mm

2: Sill ns
Dented
Over 30mm



3: Sill ns
Dented
Over 30mm

4: Qtr Panel nsr
Dented
Over 30mm



5: Panel Rear
Dented
Over 30mm

6: Qtr Panel osr
Dented
Over 30mm



7: Sill os
Dented
Over 30mm

8: Qtr Panel osr
Dented
Over 30mm



9: Door osf
Dented
Over 2 UpTo 10mm

10: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition -
Seat Condition -

Upholstery Condition -
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK