



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DK19VBL

Isuzu N75 190

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details

Reg. date	05/03/2019	VIN	JAANPR75MJ7100445	Axle Combi	4x2
Year	2019	Body Style	Dropside	Rear Suspension	Steel
Mileage	96,514 Km Warranted	MOT Due	30/06/2026	Tail Lift	Cantilever
Fuel Type	Diesel	Cab Type	DAY CAB		
Colour	BLUE/YELLOW	Gearbox	AUTOMATIC		

SERVICE SCHEDULE LIST AVAILABLE, SURROUND CAMERA SYSTEM

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Park assist camera


Photos







Condition Check



Damage Photos



1: Door nsf
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK