



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PK63FTZ

Daf LF 55.180

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	17/11/2013	VIN	XLRAE55FF0L429280	Axle Combi	4x2
Year	2013	Body Style	Box Van	Rear Suspension	Steel
Mileage	TBC	MOT Due	30/06/2026	Rear Doors	Roller
Fuel Type	Diesel	Cab Type	DAY CAB	Tail Lift	Column
Colour	ORANGE	Gearbox	AUTOMATIC		

* NON-RUNNER, TURNS OVER DOES NOT START, GEARBOX ISSUE*

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD

Photos





Condition Check



Damage Photos



1: Door Moulding ofsf
Scuffed (Unpainted)
Over 100mm



2: Door ofsf
Dented
Over 2 UpTo 10mm




3: Wing osf
Cracked
Replace

4: Bumper Front
Rusted
Over 5mm



5: Qtr Panel osr
Rusted
Over 5mm

6: Qtr Panel nsr
Rusted
Over 5mm



7: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	Fault	Gearbox 1st and Reverse Test	Fault
Brakes	Fault	Clutch Slip Test from Static	Fault
Parking Brake	Fault	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	Fault
EML light illuminated	Fault	Oil warning light illuminated	Fault
Airbag light illuminated	Fault	Service indicator light illuminated	Fault
ABS light illuminated	Fault		
Windows	OK	Radio	OK
		Steering	Fault