



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**PJ20JHF**

## Mercedes-Benz Sprinter 314 CDI

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT  
V5 To Follow

### Details

Reg. date	20/07/2020	VIN	W1V9076352P251687	CAP Below	£3,850.00
Year	2020	Body Style	Panel Van L3	Gearbox	AUTOMATIC
Mileage	256,323 Miles Warranted	MOT Due	07/04/2027	Gears	6
Fuel Type	Diesel	CAP Clean	£5,525.00		
Colour	WHITE	CAP Average	£4,800.00		

AD BLUE, SIDE LOADING DOOR

### Tyres

NSF

NSR

OSF


OSR


Spare

## Features


- Rear parking sensor
- Front electric windows

## Photos





## Condition Check



## Damage Photos



1: Wing of  
Dented  
With Paint Damage

2: Bonnet  
Dented  
With Paint Damage



3: Bonnet  
Chipped  
Multiple Chips

4: Screen Front  
Chipped  
Over 10mm




5: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm

6: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



7: Wing nsf  
Chipped  
1 To 5

8: Door nsf  
Dented  
Between 10mm + 30mm



9: Fuel Flap  
Dented  
Between 10mm + 30mm

10: Door nsf  
Dented  
Between 10mm + 30mm



11: Door nsf  
Dented  
Between 10mm + 30mm

12: Door nsr  
Dented  
With Paint Damage



13: Door Moulding nsr  
Scuffed (Unpainted)  
Over 100mm

14: Door nsr  
Scratched  
Over 25mm Thru Paint



15: Qtr Panel nsr  
Dented  
Over 30mm

16: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



17: Badgedecal Rear  
Missing  
Replace

18: Door nsr  
Dented  
Over 2 UpTo 10mm



19: Door osr  
Dented  
Over 2 UpTo 10mm

20: Qtr Panel osr  
Dented  
With Paint Damage



21: Seat Base Cover of  
 Holed  
 Over 3mm

**Interior**

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK