



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DK62WYF

MERCEDES-BENZ AXOR 1843

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details		Colour		Cab Type	
Reg. date	22/10/2012	WHITE		HIGH ROOF	SLEEPER CAB
Year	2012	VIN	WDF9440322B977580	Gearbox	AUTOMATIC
Mileage	1,493,974 Km Not Warranted	Body Style	Tractor Unit	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	31/05/2026	Rear Suspension	Air

SLIDING 5TH WHEEL



Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Digital radio
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Badgedecal Front
Missing
Replace



3: Bumper Front
Cracked
Over 25mm

4: Door nsf
Chipped
Multiple Chips



5: Wing nsf
Scratched
Over 25mm Thru Paint

6: Qtr Panel nsr
Rusted
Over 5mm




7: Qtr Panel Trim ns
Missing
Replace

8: Panel Rear
Dented
With Paint Damage



9: Qtr Panel Trim os
Broken
Replace

10: Door osf
Dented
With Paint Damage



11: Door osf
Dented
Over 30mm

12: Door osf
Scratched
Over 25mm Thru Paint



13: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition
Seat Condition

OK
Poor

Upholstery Condition
Odour

OK
-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		