

VEHICLE INSPECTION REPORT

BF23YOK

Iveco Eurocargo 120-210

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Livingston	GVW	12000kg	Cab Type	DAY CAB
Reg. date	30/08/2023	Colour	WHITE	Gearbox	MANUAL
Year	2023	VIN	ZCFAH1EF102728956	Axle Combi	4x2
Mileage	35,016 Km Warranted	Body Style	Pole Erection Unit	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	30/09/2026		

AUTOGUIDE EQUIPMENT AUGER, PALFINGER PK 9.501 SLD REMOTE CRANE (YEAR 2022) WEIGH SYSTEM, REAR VIEW CAMERA.


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD
- Air conditioning

Photos





Condition Check



Damage Photos



1: Door Moulding osf
Scuffed (Unpainted)
Over 100mm

2: Door osf
Dented
Over 2 UpTo 10mm



3: Door nsf
Dented
With Paint Damage

4: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Turbo Boosting	OK			Gearbox Static Gear Selection (engine running)	OK		
Parking Brake	OK			No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		
Windows	OK			Radio	OK		
				Steering	OK		