

VEHICLE INSPECTION REPORT

HJ72LZV

Ford Transit 350 2.0 ECOBLUE 130PS RWD

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	30/09/2022	VIN	WF0EXXTTRENJ39254	CAP Clean	£10,700.00
Year	2022	Body Style	Panel Van LWB	CAP Average	£9,875.00
Mileage	70,598 Miles TBC	Service history	Part	CAP Below	£8,475.00
Fuel Type	Diesel	Service documents	Printout	Gearbox	MANUAL
Colour	WHITE	MOT Due	29/09/2025	Gears	6

ACCIDENT DAMAGE - MAY OR MAY NOT APPEAR ON VCAR *WARNING LIGHTS ON DASH* AD-BLUE, SIDE LOAD DOOR, TOW BAR, DEADLOCKS (WITH KEYS)

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Bluetooth connection
- Central locking
- Front electric windows
- Cloth seat trim
- Drivers airbag
- Passenger airbag


Photos








Condition Check



Damage Photos



1: Unclassified
Substantial Accident Damage
Report Only



2: Qtr Panel nsr
Dented
Over 30mm



3: Bumper Rear Moulding
Broken
Replace



4: Door nsr
Dented
Over 30mm



5: Door osr
Dented
Over 30mm



6: Qtr Panel osr
Dented
Over 30mm



7: Qtr Panel osr
Poor Previous Repair
Poor Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK