

VEHICLE INSPECTION REPORT

HX72YKP

Mercedes-Benz Atego 1223

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Livingston	GVW	11990kg	Cab Type	DAY CAB
Reg. date	15/12/2022	Colour	WHITE	Gearbox	AUTOMATIC
Year	2022	VIN	W1T96700520618256	Axle Combi	4x2
Mileage	67,479 Km Warranted	Body Style	Pole Erection Unit		
Fuel Type	Diesel	MOT Due	31/01/2027		

PALFINGER PK 9.501 REMOTE CRANE (YEAR 2022), AUTOGUIDE 40PXV AUGER (YEAR 2023), POLE JACK, HEATED DRYING LOCKER, 240V POWER, AUGER EXTENSION POLE, SURROUND CAMERA SYSTEM, WEIGH SYSTEM.


Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Radio/CD
- Air conditioning


Photos







Condition Check



Damage Photos



1: Door Moulding of
Scuffed (Unpainted)
Over 100mm



2: Qtr Panel Arch Extension is
Broken
Replace



3: Door nsf
Dented
Over 2 UpTo 10mm

4: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



5: Other
N/A
N/A

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK