

VEHICLE INSPECTION REPORT

HX72YKS

Mercedes-Benz Atego 1223

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Livingston	GVW	11990kg	Cab Type	DAY CAB
Reg. date	16/02/2023	Colour	WHITE	Gearbox	AUTOMATIC
Year	2023	VIN	W1T96700520629014	Axle Combi	4x2
Mileage	49,998 Km Warranted	Body Style	Pole Erection Unit		
Fuel Type	Diesel	MOT Due	31/03/2027		

PALFINGER PK 9.501 REMOTE CRANE (YEAR 2022), AUTOGUIDE 40PXV AUGER (YEAR 2023), POLE JACK, HEATED DRYING LOCKER, 240V POWER, AUGER EXTENSION POLE, SURROUND CAMERA SYSTEM, WEIGH SYSTEM.

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD
- Air conditioning

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip



2: Door osf
Scratched
Over 25mm Not Thru Paint



3: Wing osf
Dented
With Paint Damage

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Brakes	OK	Gearbox 1st and Reverse Test	OK
Turbo Boosting	OK	Clutch Slip Test from Static	OK
		Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK		