



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HX24WSO

Mercedes-Benz Atego 816

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details

Reg. date	18/04/2024	Colour	WHITE	Cab Type	DAY CAB
Year	2024	VIN	W1T96700220666084	Gearbox	AUTOMATIC
Mileage	8,536 Km Warranted	Body Style	Pole Carrier	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	30/04/2027	Rear Suspension	Steel

HIAB X-HIDUO 062 B-2 (2 EXT) REMOTE CRANE (YEAR 2023), REAR VIEW CAMERA.

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD
- Air conditioning

Photos





Condition Check



Damage Photos



1: Door Moulding of
Scuffed (Unpainted)
Over 100mm

2: Wing of
Scratched
Up To 25mm Not Thru Paint



3: Door osf
Dented
Over 30mm

4: Door Moulding nsf
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK