

## VEHICLE INSPECTION REPORT

**HK21OBO**

### Ford Transit Custom 300 2.0 ECOBLUE 130PS LIMITED

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 Present

#### Details

Reg. date 07/05/2021

Year 2021

Mileage 40,675 Miles Not Warranted

Fuel Type Diesel

Colour SILVER

VIN WF0YXXTTGYMM36061

Body Style Panel Van SWB

MOT Due Expired

CAP Clean £14,450.00

CAP Average £13,150.00

CAP Below £11,000.00

Gearbox MANUAL

Gears 6

\*WARNING LIGHT ON DASH\* AD BLUE, SINGLE SIDE DOOR, E/MIRRORS

#### Tyres

NSF

NSR

OSF

OSR


Spare

## Features

- Front parking sensor
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows
- Leather seat trim


## Photos







## Condition Check



## Damage Photos



1: Screen Front  
Chipped  
UpTo 10mm



2: Door Mirror Assy nsf  
Broken  
Replace



3: Door nsf  
Scratched  
Over 25mm Thru Paint



4: Door nsf  
Scratched  
Over 25mm Not Thru Paint



5: Door nsr  
Hole  
Over 10mm



6: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



7: Door Mirror Assy osf  
Broken  
Replace



8: Seat Base Cover osf  
Holed  
Over 3mm

## Interior

| <b>Carpet Condition</b>  | <b>Average</b> | <b>Upholstery Condition</b>                    | <b>Average</b> |
|--------------------------|----------------|------------------------------------------------|----------------|
| <b>Seat Condition</b>    | <b>Average</b> | <b>Odour</b>                                   | <b>No</b>      |
| Engine Runs              | OK             | Gearbox 1st and Reverse Test                   | OK             |
| Brakes                   | OK             | Clutch Slip Test from Static                   | OK             |
| Parking Brake            | OK             | Gearbox Static Gear Selection (engine running) | OK             |
|                          |                | No Excessive Smoking                           | OK             |
| EML light illuminated    | OK             | Oil warning light illuminated                  | OK             |
| Airbag light illuminated | OK             | DPF light illuminated                          | OK             |
| ABS light illuminated    | OK             | Service indicator light illuminated            | OK             |