

# VEHICLE INSPECTION REPORT

**SP60VXR**

## Ford Transit Connect 200 TDCi 75ps Low Roof

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 17/11/2010

Body Style Panel Van SWB

Gears 5

Year 2010

MOT Due 23/07/2025

Doors 4

Mileage 90,176 Miles Warranted

CAP Clean £960.00

Axle Combi 4x2

Fuel Type Diesel

CAP Average £770.00

Rear Suspension Steel

Colour WHITE

CAP Below £500.00

VIN WF0TXXTPTAY71112

Gearbox MANUAL

### Tyres

NSF


NSR


OSF

OSR

Spare


### Photos







## Condition Check



## Damage Photos



1: Sill os  
Rusted  
Over 5mm



2: Bonnet  
Rusted  
Over 5mm



3: Door osf  
Dented  
Over 30mm



4: Qtr Panel osr  
Rusted  
Over 5mm



5: Qtr Panel Moulding os  
Missing  
Replace



6: Tailgate  
Dented  
Between 10mm + 30mm



7: Bumper Rear Moulding  
Scuffed (Unpainted)  
Over 100mm



8: Qtr Panel nsr  
Rusted  
Over 5mm



9: Handle Outer nsr  
Broken  
Replace

10: Door nsf  
Dented  
Over 30mm

## Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs		Fault	Gearbox 1st and Reverse Test	OK
Brakes		OK	Clutch Slip Test from Static	OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake		OK	No Excessive Smoking	OK
EML light illuminated		OK	Oil warning light illuminated	OK
Airbag light illuminated		OK	Service indicator light illuminated	OK
ABS light illuminated		OK		
Windows		OK	Radio	OK
			Steering	OK