

VEHICLE INSPECTION REPORT

SP11UXR

Ford Transit 350 2.2 TDCi 115ps FWD

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 30/03/2011

Year 2011

Mileage 123,358 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0XXXTTFXAT17514

Body Style Panel Van LWB

MOT Due 21/03/2026

CAP Clean £1,225.00

CAP Average £960.00

CAP Below £650.00

Cab Type DAY CAB

Gearbox MANUAL

Gears 6

Doors 2

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Sill os
Rusted
Over 5mm



2: Roof
Rusted
Over 5mm



3: Bonnet
Chipped
Multiple Chips



4: Wing osf
Rusted
Over 5mm



5: Door osf
Rusted
Over 5mm



6: B Post os
Rusted
Over 5mm



7: Qtr Panel osr
Rusted
Over 5mm



8: Tailgate
Dented
Over 30mm



9: Badgedecal Rear
Broken
Replace



10: Qtr Panel nsr
Dented
Over 30mm



11: B Post ns
Rusted
Over 5mm



12: Door nsf
Rusted
Over 5mm



13: Wing nsf
Rusted
Over 5mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK
Windows		OK	Radio		OK
			Steering		OK