



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

G14FGT

DAF XD 450

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	08/12/2023	VIN	XLRTGF5100G497142	Axle Combi	6x2
Year	2023	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	402,540 Km Not Warranted	MOT Due	31/12/2026	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	HIGH ROOF SLEEPER CAB		
Colour	WHITE	Gearbox	AUTOMATIC		

SURROUND CAMERA SYSTEM


Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Digital radio
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint

4: Door nsf
Scratched
Over 25mm Thru Paint



5: Wing Front Arch Extension ns
Broken
Replace

6: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



7: Panel Rear
Cracked
Replace

8: Panel Rear
Cracked
Replace



9: Other
N/A
N/A

10: Qtr Panel osr
Cracked
Replace



11: Door nsf
Scratched
Over 25mm Thru Paint

12: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



13: Door Mirror Assy osf
Broken
Replace

14: Door osf
Cracked
Replace



15: Door Mirror Assy nsf
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		