



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SJ17SYS

Mercedes-Benz Arocs 3236

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	20/06/2017	Colour	BLUE	Gearbox	AUTOMATIC
Year	2017	VIN	WDB96423020150464	Axle Combi	8x4
Mileage	185,886 Km Not Warranted	Body Style	Skiploader	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	31/07/2026		
GVW	32000kg	Cab Type	DAY CAB		

BOUGHTON LIFTING GEAR, MID STEER, SHEETING SYSTEM, REAR VIEW CAMERA.


Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm

2: Door Moulding of
Scuffed (Unpainted)
Over 100mm



3: Bonnet
Chipped
Multiple Chips

4: Bumper Front Moulding
Missing
Replace



5: Door osf
Dented
With Paint Damage

6: Qtr Panel osr
Rusted
Over 5mm



7: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK