



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

RV70DBZ

Iveco Eurocargo 75-160

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	21/10/2020	Colour	WHITE	Axle Combi	4x2
Year	2020	VIN	ZCFA875B602700487	Rear Suspension	Steel
Mileage	90,262 Km Warranted	Body Style	Box Van	Rear Doors	Roller
Fuel Type	Diesel	Cab Type	DAY CAB	Tail Lift	Column
GVW	7500kg	Gearbox	AUTOMATIC		


Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Front electric windows
- Cruise control
- Central locking
- Digital radio
- Cloth seat trim
- Air conditioning


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint

2: Bonnet
Scratched
Over 25mm Thru Paint



3: Panel Front
Scratched
Over 25mm Thru Paint

4: Door Mirror Assy nsf
Broken
Replace



5: Door nsf
Chipped
Multiple Chips

6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint

8: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



9: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition

OK

Upholstery Condition

OK

Seat Condition

Poor

Odour

-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		