



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

RV70DHU

Iveco Eurocargo 75-160

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details			
Reg. date	09/11/2020	Colour	WHITE
Year	2020	VIN	ZCFA875B902700824
Mileage	94,719 Km Warranted	Body Style	Box Van
Fuel Type	Diesel	Cab Type	DAY CAB
GVW	7500kg	Gearbox	AUTOMATIC
		Axle Combi	4x2
		Rear Suspension	Steel
		Rear Doors	Roller
		Tail Lift	Column

NO HEADLIGHTS


Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Front electric windows
- Cruise control
- Central locking
- Digital radio
- Cloth seat trim
- Air conditioning

Photos





Condition Check



Damage Photos



1: Headlamp os
Missing
Replace

2: Bumper Front Moulding
Missing
Replace



3: Bumper Front Moulding
Missing
Replace

4: Headlamp ns
Missing
Replace



5: Panel Front
Scratched
Over 25mm Thru Paint

6: Bumper Front
Scratched
Over 100mm Thru Paint



7: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel osr
 Scratched
 Over 25mm Thru Paint

10: Door osf
 Scratched
 Over 25mm Thru Paint



11: Screen Front
 Chipped
 Over 10mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		