

VEHICLE INSPECTION REPORT

RV70DFE

IVECO EUROCARGO 75-160

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Avonmouth	Colour	WHITE	Axle Combi	4x2
Reg. date	16/10/2020	VIN	ZCFA875B302700737	Rear Suspension	Steel
Year	2020	Body Style	Box Van	Rear Doors	Roller
Mileage	192,145 Km Warranted	MOT Due	31/10/2026	Tail Lift	Column
Fuel Type	Diesel	Cab Type	DAY CAB		
GVW	7500kg	Gearbox	AUTOMATIC		

WARNING LIGHTS ON DASH

Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bonnet
Chipped
Multiple Chips




3: Bonnet
Cracked
Replace

4: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: Door osf
Chipped
Multiple Chips



7: Door Mirror Assy osf
Broken
Replace

8: Moulding osf Wing
Scratched (Painted)
Over 25mm Thru Paint



9: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		