



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

RV70DFA

IVECO EUROCARGO 75E

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow


Details					
Reg. date	22/10/2020	VIN	ZCFA875B502700741	Axle Combi	4x2
Year	2020	Body Style	Box Van	Rear Suspension	Steel
Mileage	110,647 Km Warranted	MOT Due	31/01/2027	Tail Lift	Column
Fuel Type	DIESEL	Cab Type	DAY CAB		
Colour	WHITE	Gearbox	AUTOMATIC		




Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD
- Cloth seat trim
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Dash Warning Lights
Displayed
No Action

2: Carpets Front
Torn
Over 10mm



3: Bonnet
Chipped
Multiple Chips



4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



7: Door osf
Scratched
Over 25mm Thru Paint

8: Door osf
Scratched
Over 25mm Thru Paint



9: Qtr Panel osr
Hole
Over 10mm

10: Centre Console Front
Holed
Over 3mm

Interior

Carpet Condition
Seat Condition

Average
OK

Upholstery Condition
Odour

OK
-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		