



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

S15FGT

DAF XD 450

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	01/06/2023	VIN	XLRTGF5100G463640	Axle Combi	6x2
Year	2023	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	474,732 Km Not Warranted	MOT Due	30/06/2026	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	SLEEPER CAB		
Colour	WHITE	Gearbox	AUTOMATIC		

SLIDING 5TH WHEEL, SURROUND CAMERA SYSTEM




Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Front electric windows
- Cruise control
- Central locking
- Digital radio
- Cloth seat trim
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front Moulding
Missing
Replace



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint




5: Door Mirror Assy nsf
Broken
Replace

6: Panel Rear
Dented
Over 30% Of Panel



7: Door nsf
Chipped
Multiple Chips

8: Door Mirror Assy osf
Broken
Replace



9: Moulding of Wing
Missing
Replace

10: Bumper Front
Scratched
Over 100mm Thru Paint



11: Rear Panel Trim Int
Holed
Over 3mm

Interior

Carpet Condition
Seat Condition

OK
OK

Upholstery Condition
Odour

OK
-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		