

# VEHICLE INSPECTION REPORT

**PJ20PPU**

## Mercedes-Benz Sprinter 314 CDI

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date 31/07/2020

VIN W1V9106332P251269

CAP Below £8,675.00

Year 2020

Body Style Panel Van L2

Gearbox AUTOMATIC

Mileage 95,486 Miles  
Warranted

MOT Due 01/08/2025

Axle Combi 4x2

CAP Clean £11,900.00

Fuel Type Diesel

CAP Average £10,600.00

Colour WHITE

AD-BLUE, SINGLE SIDE DOOR, REAR SENSORS, E/WINDOWS  
BEEN ON FULL R&M CONTRACT FROM NEW

### Tyres

NSF

NSR


OSF

OSR

Spare


### Photos







## Condition Check



## Damage Photos



1: Wing osf  
Rusted  
Over 5mm



2: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



4: Bonnet  
Dented  
Over 30mm



5: Screen Front  
Chipped  
UpTo 10mm



6: Wing nsf  
Dented  
With Paint Damage



7: Door nsf  
Scratched  
Over 25mm Thru Paint



8: Door nsr  
Dented  
Over 30% Of Panel




9: Sill ns  
Dented  
Over 30mm




10: Door Moulding nsr  
Missing  
Replace



11: Door nsr  
Cracked  
Replace



12: Door nsr  
Dented  
With Paint Damage



13: Qtr Panel nsr  
Dented  
Over 30mm



14: Qtr Panel Trim ns  
Broken  
Replace





15: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



16: Door nsr  
Dented  
Over 30mm




17: Door osr  
Dented  
With Paint Damage



18: Lamp nsr  
Broken  
Replace



19: Lamp osr  
Broken  
Replace



20: Qtr Panel osr  
Dented  
With Paint Damage



21: Sill os  
Dented  
With Paint Damage



22: General Exterior  
Soiled  
Light



23: Door osf  
Dented  
With Paint Damage



24: Door osf  
Scratched  
Over 25mm Thru Paint



25: Carpets Front  
Holed  
Over 3mm



26: Seat Base Cover nsf  
Holed  
Over 3mm

## Interior

<b>Carpet Condition</b>	<b>Average</b>	<b>Upholstery Condition</b>	<b>Average</b>
<b>Seat Condition</b>	<b>Average</b>	<b>Odour</b>	<b>No</b>
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK