

VEHICLE INSPECTION REPORT

C354905

DON BUR BOX

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	VIN	SEPBV38GKDL061440	Brakes	Disc
Year	2013	Body Style	Box Van	Axle Combi
Mileage	TBC	Service history	Yes	Steering Combi
Fuel Type	Service documents	Printout	Rear Suspension	Air
Colour	MOT Due	31/08/2025	Rear Doors	Roller

W/O REAR FRAME CRACKED 13.6M, 4.24M, BPW, RAISE & LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



