

VEHICLE INSPECTION REPORT

RV70DCF

Iveco Eurocargo 75E16S

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Doncaster

Colour WHITE

Axle Combi 4x2

Reg. date 01/10/2020

VIN ZCFA875B702700563

Rear Suspension Steel

Year 2020

Body Style Box Van

Rear Doors Roller

Mileage 109,626 Km Warranted

Service history Yes

Tail Lift Column

Fuel Type Diesel

Cab Type DAY CAB

GVW 7500kg

Gearbox AUTOMATIC

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features

- Bluetooth connection
- Cruise control
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Missing
Replace



3: Bumper Front
 Scratched
 Over 100mm Thru Paint

4: Door Mirror Assy nsf
 Scuffed (Unpainted)
 Over 100mm



5: Screen Front
 Chipped
 Over 10mm

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		OK	Odour		-
Engine Runs	OK		No Excessive Smoking		OK
EML light illuminated	OK		DPF light illuminated		OK
ABS light illuminated	OK				