

VEHICLE INSPECTION REPORT

YO69XOW

Volvo FM 420

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Missing

Details

Reg. date 01/09/2019

Year 2019

Mileage 306,231 Km Not Warranted

Fuel Type Diesel

Colour WHITE/BLUE

VIN YV2XTW0G2KA850088

Body Style Tipper

MOT Due 30/09/2025

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 8x4

Rear Suspension Steel

THOMPSON STEEL BODY, BINOTTO TIPPING GEAR, SHEETING SYSTEM, WEIGH SYSTEM

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3



OSO4

Features


- Bluetooth connection
- Cruise control
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Door nsf
 Scratched
 Over 25mm Thru Paint



2: Seat Base Cover osf
 Soiled
 Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK

EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		