



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DY69NYG

Vauxhall Vivaro 2900 1.5 DYNAMIC 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Present

Details

Reg. date	31/12/2019	Colour	WHITE	CAP Average	£5,125.00
Year	2019	VIN	VXEVBVYHRKL7009133	CAP Below	£4,000.00
Mileage	94,253 Miles Warranted	Body Style	Panel Van L2	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	26/11/2026	Gears	6
GVW	2830kg	CAP Clean	£5,950.00		

OUTSTANDING RECALL *WARNING LIGHTS ON DASH* TWIN SIDE LOADING DOORS, E/MIRRORS


Tyres


NSF
NSR
OSF
OSR
Spare

Features


- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



3: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm

4: Door Moulding osr
Scuffed (Unpainted)
Over 100mm



5: Door Moulding osf
Scuffed (Unpainted)
Over 100mm

6: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault