



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**SM67KZN**

## Kia Ceed 1.6 CRDi ISG 2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	To Follow

Details					
Reg. date	25/01/2018	Colour	SILVER	CAP Average	£2,850.00
Year	2018	VIN	U5YHN516LJL324592	CAP Below	£2,325.00
Mileage	109,111 Miles Warranted	Body Style	Hatchback	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	07/02/2027	Gears	6
GVW	1920kg	CAP Clean	£3,325.00	Doors	5


\*ACCIDENT DAMAGE\* E/MIRRORS

Tyres
NSF
NSR
OSF
OSR
Spare

## Features

- Rear parking sensor
- Radio/CD
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Alloy wheels

## Photos






KIA		KIA MOTORS SLOVAKIA S.R.O.	
변속기 TRANSM	차축 AXLE	도어 PART	연료 TRM
7		KC	WK
051		e4*2007/46*0496	
		-U5YH516L_324592-	
		1920 kg	
		3420 kg	
		1 -1050 kg	
		2 -960 kg	

KIA MOTORS  
 GRADE: 2  
 HOME OF THE 7 YEAR WARRANTY  
 WWW.KIA.CO.UK



## Condition Check



## Damage Photos



1: Carpets Front  
Torn  
Over 10mm

2: Bonnet  
Dented  
With Paint Damage



3: Headlamp os  
Broken  
Replace

4: Bumper Front  
Cracked  
Over 25mm



5: Wing osf  
Dented  
With Paint Damage

6: Sill os  
Dented  
With Paint Damage



7: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint

8: Door nsf  
Dented  
With Paint Damage

## Interior

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK