



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

ST62MJJ

Ford Transit T300 2.2 TDCi 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	31/01/2013	VIN	WF0XXXTTFXCS83075	CAP Average	£870.00
Year	2013	Body Style	Panel Van MWB	CAP Below	£580.00
Mileage	112,735 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
GVW	3025kg	MOT Due	27/02/2027		
Colour	WHITE	CAP Clean	£1,100.00		

RADIATOR LEAKING SIDE LOAD DOOR

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Carpets Front
Torn
Over 10mm

2: Seat Base Cover of
Torn
Up To 3mm



3: Sill os
Rusted
Over 5mm

4: Bonnet
Dented
With Paint Damage



5: Roof
Rusted
Over 5mm

6: Wing osf
Rusted
Over 5mm



7: Door osf
Rusted
Over 5mm

8: B Post os
Rusted
Over 5mm



9: Qtr Panel osr
Rusted
Over 5mm

10: Tailgate
Dented
Over 30mm



11: Qtr Panel nsr
Dented
With Paint Damage

12: Door nsr
Dented
With Paint Damage



13: Door nsf
Rusted
Over 5mm

14: Sill ns
Rusted
Over 5mm

Interior

Carpet Condition	Average	Upholstery Condition	-
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK