



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BT15KYR

IVECO DAILY 70-170

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details			
Reg. date	08/06/2015	Fuel Type	Diesel
Year	2015	Colour	WHITE
Mileage	161,286 Km Warranted	VIN	ZCFC270C405011055
		Body Style	Panel Van LWB
		Service history	Yes
		Gearbox	Manual

AD-BLUE, 150KG SWINGLIFT, AIR COMPRESSOR EQUIPMENT & POWER OUTLETS


Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Digital radio
- Passenger airbag
- Radio/CD
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Panel Front
Cracked
Replace



3: Roof
Dented
With Paint Damage

4: Wing nsf
Dented
With Paint Damage



5: Door nsf
Chipped
Over 5mm

6: Qtr Panel nsr
Dented
Over 30mm



7: Qtr Panel nsr
Dented
With Paint Damage

8: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



9: Door nsr
Dented
Over 30mm

10: Door osr
Dented
With Paint Damage



11: Door nsr
Chipped
Multiple Chips

12: Door osr
Chipped
Multiple Chips



13: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

14: Wing osf
Rusted
Over 5mm



15: Seat Base Cover nsf
Soiled
Heavy

16: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition

OK

Upholstery Condition

OK

Seat Condition

Poor

Odour

-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		