

VEHICLE INSPECTION REPORT

C307066

DON BUR CURTAINSIDE

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date		Colour	YELLOW	Axle Combi	Tri
Year	2010	VIN	SEPPM38HPAL058775	Rear Suspension	Air
Mileage	TBC	MOT Due	31/10/2025	Rear Doors	Barn
Fuel Type		Brakes	Drum		

13.6M, 4.45M, BPW, RAISE & LOWER VALVE

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



