

VEHICLE INSPECTION REPORT

FL13XWF

Iveco Daily 65C17

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 30/05/2013

Year 2013

Mileage 101,148 Km Not Warranted

Fuel Type Diesel

Colour RED

VIN ZCFC65C1105953659

Body Style Tipper

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x4

Rear Suspension Steel

LANCASHIRE STEEL BODY TIPPER

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features


- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Door nsf
Chipped
Multiple Chips



3: Door osf
Chipped
Multiple Chips



4: Door Mirror Assy osf
Broken
Replace



5: Door Pad osf
Soiled
Heavy



6: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		