

VEHICLE INSPECTION REPORT

PJ66BLF

Daf LF 150

Non Runner
Inspection

Serious Damage?	No	Vehicle	
		VAT	Plus VAT
		V5	Present

Details

Reg. date	07/11/2016	Colour	RED	Gearbox	MANUAL
Year	2016	VIN	XLRAEL1500L459479	Axle Combi	4x2
Mileage	Not Showing	Body Style	Box Van	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	31/07/2026	Tail Lift	Cantilever
GVW	7500kg	Cab Type	DAY CAB		

NON-RUNNER - NO POWER MOT SHOWS 923,943 KM 21/07/2025

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Dented
Over 30mm



3: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

4: Door nsf
Scratched
Over 25mm Not Thru Paint



5: Wing nsf
Scratched
Over 25mm Thru Paint

6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Door osf
Chipped
Multiple Chips

8: Door osf
Scratched
Over 25mm Thru Paint




9: Door osf
Chipped
1 To 5

10: Moulding osf Wing
Scratched (Painted)
Over 25mm Thru Paint



11: Number Plate Front
Broken
Replace

12: Carpets Front
Holed
Over 3mm



13: Fascia Trim
Damaged
Replace

14: Switches And Controls
Broken
Replace

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	Fault		